

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM ^(PI) MAP

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☒ Email ☐ Mail ☐ Hand Delivery		Postmark (mail only)	Date Received 9-18-2023	Al Number 82416
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O = ORIGINAL				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D = Demo				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Building # 120				
Address: 166 Fifth Avenue				
City: Greenville		State: MS	Zip: 38701	
Site Location: Greenville Airport Building # 120		Tel: 662-378-3730		
Building Size: 13,000 SF		# of Floors: 1	Age in Years: 40 +	
Present Use: VACANT		Prior Use: Air port PERSONNEL OFFICE		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Greenville Airport City of Greenville, MS				
Address: 166 Fifth Avenue				
City: Greenville		State: MS	Zip: 38701	
Contact: Gary Vaughan JR.		Tel: 662-378-3730		
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: Delta City		State: MS	Zip: 39061	
Contact: Jimmy Bell		Tel: 662-820-2124		
Certification Number: ABC-00001282		Expiration Date: 1/5/24		
OTHER OPERATOR: Gary Vaughan JR, Construction, Inc.				
Address: 27 ANNE DRIVE-IN ROAD				
City: Leland		State: MS	Zip: 38756	
Contact: Gary Vaughan JR.		Tel: 662-378-3730		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: 7/18/23		
Inspector: Brad McKnight		Certification Number: ABI-00001685	Expiration Date: 1/7/24	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: FLOOR TILE/MASTIC, WALLS, CEILING, ROOF MATERIALS AND WINDOWS, MASONRY. All samples were sent to QUANTUM LABORATORIES AND ANALYSIS using the PLM method				
VII. QUANTITY OF RACM TO BE REMOVED: Floor tile/mastic, window glazing contains Asbestos 52 Windows with Glazing, 12,000 SF of Floor tile/mastic				
Pipes (LN FT): 0	Surface Area (SQ FT): 12,000 Floor tile		Volume of Facility Components (CU FT): 0	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ☒		Category II: ☐		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10/11/23		Complete: 10/23/23		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 10/23/23		Complete: 12/23/23		

(PL)

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Wet Method, Containment, D-cont unit, Neg-Air units, Signs, Fog Sprayer, Independent Air Monitor.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: PREP WORK AREA, PLACE SIGNS AT ALL ENTRANCE, NEG-AIR, WET AND REMOVE FLOOR TILE/MASTIC, CLEAN-UP, GET AIR CLEARANCE. REMOVE WINDOWS FROM OUT SIDE. PLACE 6 mil poly on the inside. WRAP ALL WINDOWS AND TAPE WITH 6 mil poly. PLACE All debris into lined dumpster.

XIII. WASTE TRANSPORTER #1

Name: W H & D, Inc.

Address: P.O. Box 870

City: Leland

State: MS

Zip: 38756

Contact Person: Tommy Hendrix

Tel: 662-686-4184

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Big River Landfill (Republic Services)

Address: 48 Landfill Road

City: Leland

State: MS

Zip: 38756

Contact Person: ALEIGHA JOHNSON (SPECIAL WASTE)

Tel: 601-420-8248

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:
CONTINUE UNDER CONTAINMENT, NEG-AIR, WET WORK AREA, COVER WITH 6 MIL POLY, STOP WORK, CONTACT OWNER/MDEQ OF CHANGE, AWAIT MDEQ DIRECTIONS.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

JIMMY DELL

Type or Print Name

(Signature of Owner/Operator)

4/14/23

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Robert Page

Type or Print Name

Robert Page

(Signature of Owner/Operator)

4/14/23

(Date)