



MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

MAP

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 09-26-2023	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Detached Garage removal FT & Demo both structures				
Address: 1483 Beech Springs Road				
City: Tupelo Saltillo		State: MS	Zip: 28804 38866	
Site Location: 1483 Beech Springs Road			Tel: 662-213-9454	
Building Size: Appx 1,000 SF		# of Floors: 1	Age in Years: 50+	
Present Use: Vacant		Prior Use: Detached Parking Garage for adjacent home & home		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Mainland Retail, LLC				
Address: 118 16 th Ave. S				
City: Nashville		State: TN	Zip: 37203	
Contact: Marc Messier			Tel: 205-588-5099	
ASBESTOS REMOVAL CONTRACTOR: Edward Clay - EAC Environmental				
Address: 4546 Cal-Steens Road				
City: Caledonia		State: MS	Zip: 39740	
Contact: Edward Clay			Tel: 662-386-6386	
Certification Number: ABC-00005192			Expiration Date: 11-05-2023	
OTHER OPERATOR: Hodges Construction				
Address: 1281 CR 811				
City: Saltillo		State: MS	Zip: 38866	
Contact: Felix Rutledge			Tel: 662-401-3180	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 03-09-23	
Inspector: Megan N. Sweatt		Certification Number: ABI-00011940	Expiration Date: 11-02-23	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:				
Drywall and textures, Ceiling Tile, Floor Tile, Sealants and Insulation PLM Analytical Method				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):	Surface Area (SQ FT): Appx 450		Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10-10-23			Complete: 10-10-23	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 10-11-23			Complete: 10-16-23	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:		
Remove floor tile with floor scrapers using Wet Method attached garage only & Demo both structures		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:		
Contain work area, use air scrubber, airless sprayer with surfactant, wet method removal, double bag, 6 mil poly		
XIII. WASTE TRANSPORTER #1		
Name: EAC Environmental		
Address: 4546 Cal-Steens Road		
City: Caledonia	State: MS	Zip: 39740
Contact Person: Edward Clay	Tel: 662-386-6386	
WASTE TRANSPORTER #2		
Name: Waste Pro		
Address: 1600 12th Street South		
City: Columbus	State: MS	Zip: 39701
Contact Person: RuthAnn Faris	Tel: 662-328-5528	
XIV. WASTE DISPOSAL SITE RoBo Landfill		
Name: RoBo Landfill		
Address: 6447 Wahalak Road		
City: Scooba	State: MS	Zip: 39358
Contact Person: Roland Edmonds	Tel: 662-798-4795	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name:		Title:
Authority:		
Date of Order (MM/DD/YY):		Date Ordered to Begin (MM/DD/YY):
XVI. FOR EMERGENCY RENOVATIONS:		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:		
Contain material, notify owner, and contact MDEQ		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Edward A. Clay		09-26-23
Type or Print Name	(Signature of Owner/Operator)	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS		
CORRECT: Edward A. Clay		09-26-23
Type or Print Name	(Signature of Owner/Operator)	(Date)