


MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: □Email □Mail Hand Delivery Postmark (n		Received 2023 Al Number				
	II. Type of Notification (O=Original R=Revised C=Canceled A= Annual) II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):					
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Bldg. Name: Residential House						
Address: 2955 SHEILA DR.						
City: JACKSON	State: MS	Zip: 39209				
Site Location: Same as above		Tel:				
Building Size: 1294	# of Floors: 1	Age in Years: 66				
Present Use:	Prior Use:					
IV. FACILITY INFORMATION (Identify owner, asbestos rem	oval contractor, and other ope	erator)				
OWNER NAME: STATE OF MISS						
Address: P O BOX 136						
City: JACKSON	State: MS	Zip: 39205-0136				
Contact: City of Jackson		Tel: 601-960-1054 or 601-960-2470				
asbestos removal contractor: Anderson E	nviron m ental	·				
Address:870 Foley Street						
_{city:} Jackson	State: MS	z _{ip:} 39202				
contact: Daryl Anderson		те!:601-354-4400				
Certification Number:	Expi	ration Date:				
отнек орекаток: X quisite Lawncare LLC		-				
Address:210 Meadowbrook Rd, Suite 102						
_{city:} Jackson	State: M S	zip: 39206				
contact:Steven Jones		Tel: 769-226-9237				
V. WAS SITE INSPECTED TO DETERMINE PRESENCE O						
WAS ASBESTOS PRESENT? (Yes/No): YES Inspection Date: 4/6/2020						
Inspector: SAMANTHA GRAVES Certifica VI. SUSPECT MATERIALS SAMPLED AND PROCEDURE	tion Number: ABI-0000982	25 Expiration Date: 11/17/2022				
Patricia Carlo Car		A-9-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-				
EPA 600/R-93-/116 BULK POLARIZED LIGHT MICROSCOPY (EAS) SHINGLES, SHEETROCK, VINYL SIDING, FELT PAPER, FLOOR TILE						
VII. QUANTITY OF RACM TO BE REMOVED:						
Diagram (INIET)	a (SQ FT): 1294	Volume of Facility Components (CU FT):				
		volume of Facility Components (CO F1).				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:						
Category I: Category II: IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10/03/2023 Complete: 10/05/2023						
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10/03/2023 Complete: 10/05/2023 X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 10/06/2023 Complete: 11/13/2023						
A. SCHEDULED DATES DEMO/KENOVATION (MM/DD/Y)) Start.	Ahithora II.				



infooxquisile lawn caret

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:				
abatement and demo of abandoned houswe				
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE:	NG CONTROLS TO BE USE	D TO PREVENT EMISSIONS OF ASBESTOS AT THE		
Area barricaded with asbestos sign and danger	tape, removed using	WET method and ACM and poly bags.		
XIII. WASTE TRANSPORTER #1				
_{Name:} X quisite Lawncare LLC				
Address: 210 Meadowbrook Rd, Suite 102				
_{city:} Jackson	State: MS	zip: 39206		
Contact Person:Steven Jones		Tel: 769-226-9237		
WASTE TRANSPORTER #2				
Name:SAME				
Address:				
City:	State:	Zip:		
Contact Person:		Tel:		
XIV. WASTE DISPOSAL SITE				
Name: Allied Waste Little Dixie Landfill				
Address: 1718 N Countyline Rd				
_{City:} Ridgeland	State: M S	Zip:39157		
Contact Person:		Tel:601-982-9488		
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGEN	CY, PLEASE IDENTIFY THE	AGENCY BELOW:		
Name: Samantha Graves Title: Manager				
Authority: City of Jackson				
Date of Order (MM/DD/YY): 7/31/23 Date Ordered to Begin (MM/DD/YY):				
XVI. FOR EMERGENCY RENOVATIONS:				
Date and Hour of Emergency (MM/DD/YY):				
Description of the sudden unexpected event:				
Explanation of how the event caused unsafe conditions or would structure is a menace to the public safety and to bus stop & prostitution				
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLE				
Halt all work and notify proper authorities				
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS				
Steven Jones		09/27/2023		
Type or Print Name	(Signature of Owner/Operator)	(Date)		
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRI Steven Jones	ECT:	09/27/2023		
Type or Print Name	(Signature of Owner/Operator)	(Date)		

1.0

Environmental Analytical Services, LLC

13201 Northwest Freeway, Suite 520 Houston, Texas 77040 phone 713-343-4017 | fax 713-934-9942 www.easlabs.com | facebook.com/easlabs | info@easlabs.com

Test: EPA 600/R-93/116 **Polarized Light Microscopy**

Client Information:

Project:

Date Analyzed: 08/07/2023 05:13 PM

City of Jackson

2955 Sheila Dr.

Date Received: 08/02/2023 09:00 AM

200 S President St Jackson, MS 39201

CE-21-318

Phone: 601-960-1054

EAS Job: 23080404

TAT Requested: 3 Days

Vincent

Microscope:

Olympus-CH-40

E-Mail: mcdonaldv@city.jackson.ms.us

Attn: McDonald

Sample # Lab ID #	Layer	Sample Description	Asbestos Detected (Yes/No)	Asbestos Mineral Percent	Non-Asbestos Fibers	Non-Fibrous Material
1 23080404.01	A	Black/Gray Fibrous Shingle Homogeneous	NO	None Detected	Cellulose 30% Fiberglass 10%	Asphaltic Matrix 60%
2 23080404.02	Α	Brown/White Fibrous Sheetrock Non-Homogeneous	NO	None Detected	Cellulose 30%	Gypsum 70%
3 23080404.03	Α	Gray/Yellow Granular Transite Siding Homogeneous	YES	Chrysotile 40%		Other Non-Fibrou
4 23080404.04	Α	Black Fibrous Felt Paper Homogeneous	NO	None Detected	Cellulose 60%	Adhesive 40%
5 23080404.05	А	Green/White Granular Ceramic Tile Homogeneous	NO	None Detected		Other Non-Fibrou 100%

NVLAP Lab Code: 200784-0 TDSHS License No. 300373

LDEQ LELAP Certificate No: 04161, Agency Interest No. 149571

Some samples (floor tiles, surfacing, etc.) may contain fibers too small to be detectable by PLM. TEM Chatfield analysis of bulk material is recommended in this case. All asbestos percentages are based on some samples (noor uses, surfacing, etc.) may contain notes too smart to be detectable by PLM. Then Chatterid analysis of outs material is recommended in this case. An aspectic percentages are based on calibrated visual estimates traceable to NIST standards for regulated asbestos types. Analysts' percentages fall within a range of acceptable percentages, depending on the actual concentratiation of asbestor. This test report relates only to the items tested. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. This report may not be reproduced except in full without permission from Environmental Analytical Services.

These results are submitted pursuant to EAS' current terms of sale, including the company's standard warranty and limitation of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, EAS will store the samples for a period of ninety (90) days before discarding. Percent ranges reported are estimates and not absolute percent range values.

Analyzed By:

Arthur Hernandez

Approved Signatory:

Arthur Hernandez



HindsCountyMs.com





Landroll Detail

Parcel Number		Map Reference Number		
304-111		661.00 1 47.00 Pr	ew Ma <u>p</u> operty Taxes s Map	
Subdivision No.		Homestead Exemption Account Numbers		
1863				
Assessed Owner		Assessed Values		
STATE OF MISS		Land Value	0	
		Improvement Value	0	
		Total	0	
		Appraised Values		
Location		Land Value	0	
2955 SHEILA DR		Improvement Value	0	
Legal Description		Total	0	
LOT 12 BLK A WEST END HGTS PT 1		Building Info.		
MATURED FOR 2019 TAXES		Туре	RES	
		Base Area	1,188	
		Adjusted Area	1,294	
		Year Built	1957	
		Deed Info.		
		Book & Page	-	
Acreage Info.		Date	00/00/0000	
Cultivated Acres	0.00			
Uncultivated Acres	0.00			

Back Search