

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 12-14-23	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O = ORIGINAL				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R= RENOVATION ROOF REPLACEMENT				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: USPS BATESVILLE - MAIN OFFICE				
Address: 375 LAKEWOOD DR.				
City: BATESVILLE	State: MS	Zip: 38606-9998		
Site Location: 375 LAKEWOOD DR., BATESVILLE, MS		Tel: 336-727-4534		
Building Size: 18000 SF.	# of Floors: 1	Age In Years: 60 + -		
Present Use: U.S. POST OFFICE SERVICES		Prior Use: U.S. POST OFFICE SERVICES		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: UNITED STATES POSTAL SERVICES				
Address: 375 LAKEWOOD DRIVE				
City: BATESVILLE	State: MS	Zip: 38606-9998		
Contact: GARY KURTH			Tel: 336-727-4534	
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA CITY	State: MS	Zip: 39061		
Contact: JIMMY BELL			Tel: 662-820-2124	
Certification Number: ABL-00001282	Expiration Date: 1/5/2024		1/4/2024	
OTHER OPERATOR: AAR OF NORTH CAROLINA, INC				
Address: 655 PEDDYCORD RD.				
City: KERNERSVILLE, NC	State: NC	Zip: 27284		
Contact: GARY KURTH			Tel: 336-727-4534	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: 5/5/2021		
Inspector: EFREN PEREZ RIVERA	Certification Number: ABE-00009780	Expiration Date: 2/12/22 1/17/2024		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:				
ROOFING MATERIALS, PIPE INSULATION, PATCH ROOFING BROWN FIBER INSULATION YELLOW FOAM BOARD INSULATION WERE TAKEN SAMPLES WERE TAKEN AND SHIPPED TO - EMSL ANALYTICAL, INC. 200 ROUTE 130 NORTH CINNAMINSON, NJ 08017 TESTING USING THE PLM METHOD				
VII. QUANTITY OF RACM TO BE REMOVED: APPROXIMATELY 2100 SF OF PARAPET WALL FLASHING FROM 3 AREAS				
Pipes (LN FT): 0	Surface Area (SQ FT): 2100 SF	Volume of Facility Components (CU FT): 0		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ✓	Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 1/16/24		Complete: 1/20/24		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 1/21/24		Complete: 2/21/24		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Wet method, Chisel Blade, Bag, AREA Air Monitoring/CLEARANCE
PLACE BAGS INTO SKY LIFT Bucket, PLACE INTO Lined Dumpster.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: Wet materials using Hook Knives To Cut in MANAGING SECTIONS, WRAP IN 6 m.z. poly, TAPE/TAQ. Lower FROM ROOF using SKYLIFT. PLACE INTO Lined Dumpster. HAVE Air monitor/Inspector ON SITE AT ALL TIME.

XIII. WASTE TRANSPORTER #1

Name: Replubic Services

Address: 1035 Old Brandon Rd.

City: Flowood

State: MS

Zip: 39232

Contact Person: MIKE RALEY

Tel: 601.613.8671

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: TUNICA LANDFILL WASTE MANAGEMENT OF TUNICA

Address: 6035 Bowdre Rd.

City: Tunica-Robinsonville

State: MS

Zip: 38664

Contact Person: CARL SIMMONS

Tel: 662-363-2282

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: stop work, contact owner/MDAQ of change. Erect a Containment Cage over work area with NEG-Air IF possible.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

12/14/23

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

12/14/23

(Date)