

REV

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 3/29/2024	AI Number 78975
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Residential House				
Address: 2955 SHEILA DR.				
City: JACKSON		State: MS	Zip: 39209	
Site Location: Same as above			Tel:	
Building Size: 1294		# of Floors: 1	Age in Years: 66	
Present Use:		Prior Use:		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: STATE OF MISS				
Address: P O BOX 136				
City: JACKSON		State: MS	Zip: 39205-0136	
Contact: City of Jackson			Tel: 601-960-1054 or 601-960-2470	
ASBESTOS REMOVAL CONTRACTOR: ANDERSON ENVIRONMENTAL				
Address: 870 FOLEY STREET				
City: JACKSON		State: MS	Zip: 39202	
Contact: DARYL ANDERSON			Tel:	
Certification Number: ABI-00002173			Expiration Date: 10/27/2024	
OTHER OPERATOR: XQUISITE LAW NCARE LLC				
Address: 210 MEADOW BROOK RD, SUITE 102				
City: JACKSON		State: MS	Zip: 39206	
Contact: STEVEN JONES			Tel: 769-226-9237	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 4/6/2020	
Inspector: SAMANTHA GRAVES		Certification Number: ABI-00009825	Expiration Date: 11/17/2022	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:				
EPA 600/R-93-/116 BULK POLARIZED LIGHT MICROSCOPY (EAS) SHINGLES, SHEETROCK, VINYL SIDING, FELT PAPER, FLOOR TILE				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):		Surface Area (SQ FT): 1294	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 04/08/2024			Complete: 04/10/2024	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 04/11/2024			Complete: 04/18/2024	

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

A batement and dem o of abandoned house

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

A rea barricaded w ith asbestos sign and danger tape, rem oved using W E T m ethod and A C M and poly bags.

**XIII. WASTE TRANSPORTER #1**

Name: X Q U I S I T E L A W N C A R E L L C

Address: 210 M E A D O W B R O O K R D , S U I T E 102

City: J A C K S O N

State: M S

Zip: 39206

Contact Person: S T E V E N J O N E S

Tel: 769-226-9237

WASTE TRANSPORTER #2 S A M E

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: A L L I E D W A S T E L I T T L E D I X I E L A N D F I L L

Address: 1718 N C O U N T Y L I N E R D

City: R I G E L A N D

State: M S

Zip: 39157

Contact Person:

Tel: 601-982-9488

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name: S a m a n t h a G r a v e s

Title: M a n a g e r

Authority: C i t y o f J a c k s o n

Date of Order (MM/DD/YY): 3/25/2024

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:**

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

structure is a m enace to the pub lic safety and w elfare of the com m unity; poses danger to school children at the bus stop & prostitution


**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:**

H a l t a l l w o r k a n d n o t i f y p r o p e r a u t h o r i t i e s

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

Steven Jones

Type or Print Name



(Signature of Owner/Operator)

03/29/2024

(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:**

Steven Jones

Type or Print Name



(Signature of Owner/Operator)

03/29/2024

(Date)



**Environmental  
Analytical  
Services, LLC**

13201 Northwest Freeway, Suite 520  
Houston, Texas 77040  
phone 713-343-4017 | fax 713-934-9942  
www.easlabs.com | facebook.com/easlabs | info@easlabs.com

**Test: EPA 600/R-93/116  
Polarized Light Microscopy**

**Client Information:**

City of Jackson  
200 S President St  
Jackson, MS 39201  
Phone: 601-960-1054  
E-Mail: mcdonaldv@city.jackson.ms.us

**Project:**

2955 Sheila Dr.  
CE-21-318  
EAS Job: 23080404  
Attn: Vincent  
McDonald

**Date Analyzed:** 08/07/2023 05:13 PM

**Date Received:** 08/02/2023 09:00 AM

**TAT Requested:** 3 Days

**Microscope:** Olympus-CH-40

Sample # Lab ID #	Layer	Sample Description	Asbestos Detected (Yes/No)	Asbestos Mineral Percent	Non-Asbestos Fibers	Non-Fibrous Material
1 23080404.01	A	Black/Gray Fibrous Shingle Homogeneous	NO	None Detected	Cellulose 30% Fiberglass 10%	Asphaltic Matrix 60%
2 23080404.02	A	Brown/White Fibrous Sheetrock Non-Homogeneous	NO	None Detected	Cellulose 30%	Gypsum 70%
3 23080404.03	A	Gray/Yellow Granular Transite Siding Homogeneous	YES	Chrysotile 40%		Other Non-Fibrous 60%
4 23080404.04	A	Black Fibrous Felt Paper Homogeneous	NO	None Detected	Cellulose 60%	Adhesive 40%
5 23080404.05	A	Green/White Granular Ceramic Tile Homogeneous	NO	None Detected		Other Non-Fibrous 100%

NVLAP Lab Code: 200784-0

TDSHS License No. 300373

LDEQ LELAP Certificate No: 04161, Agency Interest No. 149571

**Notes:**

Some samples (floor tiles, surfacing, etc.) may contain fibers too small to be detectable by PLM. TEM Chatfield analysis of bulk material is recommended in this case. All asbestos percentages are based on calibrated visual estimates traceable to NIST standards for regulated asbestos types. Analysts' percentages fall within a range of acceptable percentages, depending on the actual concentration of asbestos. This test report relates only to the items tested. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. This report may not be reproduced except in full without permission from Environmental Analytical Services.

These results are submitted pursuant to EAS' current terms of sale, including the company's standard warranty and limitation of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, EAS will store the samples for a period of ninety (90) days before discarding. Percent ranges reported are estimates and not absolute percent range values.

**Analyzed By:**

Arthur Hernandez

**Approved Signatory:**

Arthur Hernandez



## Landroll Detail

Parcel Number	Map Reference Number
304-111	661.00 1 47.00
Subdivision No.	Homestead Exemption Account Numbers
1863	
Assessed Owner	Assessed Values
<a href="#">STATE OF MISS</a>	Land Value <span style="float: right;">0</span>
	Improvement Value <span style="float: right;">0</span>
	Total <span style="float: right;">0</span>
Location	Appraised Values
2955 <a href="#">SHEILA DR</a>	Land Value <span style="float: right;">0</span>
Legal Description	Improvement Value <span style="float: right;">0</span>
LOT 12 BLK A WEST END HGTS PT 1 MATURED FOR 2019 TAXES	Total <span style="float: right;">0</span>
	Building Info.
	Type <span style="float: right;">RES</span>
	Base Area <span style="float: right;">1,188</span>
	Adjusted Area <span style="float: right;">1,294</span>
	Year Built <span style="float: right;">1957</span>
	Deed Info.
	Book & Page <span style="float: right;">-</span>
	Date <span style="float: right;">00/00/0000</span>
Acreage Info.	
Cultivated Acres <span style="float: right;">0.00</span>	
Uncultivated Acres <span style="float: right;">0.00</span>	

[Back](#) [Search](#)

