

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

<b>MDEQ Use Only:</b> <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		<b>Postmark (mail only)</b>	<b>Date Received</b> 4/05/2024	<b>AI Number</b>
<b>I. Type of Notification</b> (O=Original R=Revised C=Canceled A= Annual): <input type="radio"/>				
<b>II. TYPE OF OPERATION</b> (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): <input type="radio"/> D				
<b>III. FACILITY DESCRIPTION</b> (Include building name, number and floor or room number):				
Bldg. Name: Pascagoula Ice House				
Address: 3708 Pascagoula St				
City: Pascagoula		State: MS	Zip: 39567	
Site Location: same as above			Tel: 504-884-3171	
Building Size: 15,456 SF		# of Floors: 2	Age in Years: 120	
Present Use: Vacant		Prior Use: Old Ice House		
<b>IV. FACILITY INFORMATION</b> (Identify owner, asbestos removal contractor, and other operator)				
<b>OWNER NAME:</b> In Sznc Holdings LLC				
Address: 1100 Poydras				
City: New Orleans		State: LA	Zip: 70163	
Contact: Nick Condon			Tel: 504-884-3171	
<b>ASBESTOS REMOVAL CONTRACTOR:</b> Specialty Abatement Services, Inc.				
Address: PO Box 15925				
City: Hattiesburg		State: MS	Zip: 39404	
Contact: William Stamps			Tel: 601-264-5550	
Certification Number: ABC-00001660			Expiration Date: 2/23/2025	
<b>OTHER OPERATOR:</b> Jack Ferrill's Heavy Equipment				
Address: 4222 Ingalls Ave.				
City: Pascagoula		State: MS	Zip: 39581	
Contact: Jack Ferrill			Tel: 228-216-7176	
<b>V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS?</b> (Yes/No): Yes				
<b>WAS ASBESTOS PRESENT?</b> (Yes/No): Yes			Inspection Date: 1/12/2022	
Inspector: Reginald Sampson		Certification Number: ABI-00001921	Expiration Date: 9/8/2022 07/27/2024	
<b>VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:</b>				
Floor Tile, Mastics , caulk, drywall w/ joint compound, Ceiling Tile, plaster, cork, roofing materials Bulk samples were collected and read by PLM at EMSL				
<b>VII. QUANTITY OF RACM TO BE REMOVED:</b>				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
<b>VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:</b>				
Category I: Roof Flashing (Gray paint) 600 LF			Category II:	
<b>IX. SCHEDULED DATES ASBESTOS REMOVAL</b> (MM/DD/YY) Start: 4/18/2024			Complete: 4/18/2024	
<b>X. SCHEDULED DATES DEMO/RENOVATION</b> (MM/DD/YY) Start: 4/18/2024			Complete: 4/30/2024	

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

Roof is not safe for occupancy. Building will be laid down by demo contractor . Flashing will be removed from material on ground.

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

All ACM will Wetted and removed . Waste will be placed in clear , labeled , poly bags and a placed in properly lined container for disposal.

**XIII. WASTE TRANSPORTER #1**

Name: Specialty Abatement Services, Inc.

Address: PO Box 15925

City: Hattiesburg

State: MS

Zip: 39404

Contact Person: William H. Stamps

Tel: 601-264-5550

**WASTE TRANSPORTER #2**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: Pine Belt Regional Landfill

Address: Hwy 29 N.

City: Runnelstown

State: MS

Zip: 39465

Contact Person: James A. "Tony" Harrison, MBA

Tel: 601-545-6676

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:**

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:**

All work will stop. MDEQ will be notified.

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

Anthony Bryant

Type or Print Name

(Signature of Owner/Operator)

4/5/2024

(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:**

Anthony Bryant

Type or Print Name

(Signature of Owner/Operator)

4/5/2024

(Date)