

REV

(51)

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 8/20/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):			R = Revised start Date	
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):			D = DEMO	
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: SUNFLOWER COUNTY JUSTICE COURT BUILDING (Through out Building)				
Address: 202 MAIN STREET				
City: INDIANOLA	State: MS	Zip: 38751		
Site Location: 202 MAIN STREET ANNEX BUILDING			Tel: 601-597-2724	
Building Size: 5,500 SF.	# of Floors: 1	Age in Years: 50 + -		
Present Use: VACANT	Prior Use: JUSTICE COURT BUILDING			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: SUNFLOWER COUNTY BOARD OF SUPERVISORS				
Address: 200 MAIN ST./ P.O. BOX 988				
City: INDIANOLA	State: MS	Zip: 38751		
Contact: MARY HART (COUNTY ADMINISTRATOR)			Tel: 662-887-2881	
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA CITY	State: MS	Zip: 39061		
Contact: JIMMY BELL			Tel: 662-820-2124	
Certification Number: ABL-00001282		Expiration Date: 12/15/24		
OTHER OPERATOR: SUNFLOWER COUNTY BOARD OF SUPERVISORS (MAINTENANCE DEPT.)				
Address: PO BOX 988				
City: INDIANOLA	State: MS	Zip: 38751		
Contact: MARY HART (COUNTY ADMINISTRATOR)			Tel: 662-887-2881	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 6/11/24	
Inspector: PAUL ANDERSON	Certification Number: ABL-00001686	Expiration Date: 5/31/25		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: DROP CEILING, COVE BASE, WALL PAPER, FLOOR TILE/MASTIC, CARPET, WINDOW PUTTY, ROOF SHINGLES, AND SHIPPED TO/SUBMITTED TO EUROFIN/ CAROLINA ENVIRONMENTAL LABS, INC., CARY, NORTH CAROLINA TO BE ANALYSED USING THE PLM METHOD. Findings: Asbestos Containing Floor Tile/Black mastic. (nonfriable)				
VII. QUANTITY OF RACM TO BE REMOVED: 5,000 SF. THROUGH OUT BUILDING NONFRIABLE ASBESTOS CONTAINING FLOOR TILE/MASTIC.				
Pipes (LN FT): 0	Surface Area (SQ FT): 5,000 SF.	Volume of Facility Components (CU FT): 0		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: <input checked="" type="checkbox"/>		Category II: <input type="checkbox"/>		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 9/4/24			Complete: 9/7/24	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 9/10/24			Complete: 11/10/24	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Wet Method, Neg-Air, D-CON unit, Air Clearance, Containment,

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

PREP SITE, SIGNS, 6 MIL POLY OVER WINDOWS/DOORS INSIDE, PLACE NEG-AIR UNITS, PLACE D-CON UNIT IN REAR, PLACE LINED DUMPSTER IN REAR, WET, REMOVE, BAG, DROP-TAG BAGS, TAPE CLOSE, REMOVE MASTIC, DOUBLE BAG, CLEANUP, HEPA-VAC. AWAIT AIR CLEARANCE.

XIII. WASTE TRANSPORTER #1

Name: WASTE HAULING AND DISPOSAL, INC. (WH+D)
Address: P.O. BOX 870
City: LELAND State: MS Zip: 38756
Contact Person: Tommy Hendrix Tel: 662-347-0052

WASTE TRANSPORTER #2 N/A

Name:
Address:
City: State: Zip:
Contact Person: Tel:

XIV. WASTE DISPOSAL SITE

Name: Big River Landfill (Republic Services)
Address: 52 Landfill Rd.
City: Leland State: MS Zip: 38756
Contact Person: Aleshia Johnson Tel: 662-332-7927

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: Title:
Authority:
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):
Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO POWDER:

Stop Abatement, Remain under Containment/Neg-Air, Contact owner/MDEQ of Change, Follow MDEQ Directions.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell Type or Print Name
Jimmy Bell Signature of Owner/Operator
8/20/24 Date

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell Type or Print Name
Jimmy Bell Signature of Owner/Operator
8/20/24 Date