

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 10/03/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): <input type="radio"/>				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): 5 bldgs on site				
Bldg. Name: 138 N Wheatley Site				
Address: 138 N Wheatley St				
City: Ridgeland		State: MS	Zip: 39157	
Site Location:			Tel: n/a	
Building Size: 12,000 s/f total		# of Floors: 1	Age in Years: 60+/-	
Present Use: vacant		Prior Use: chemical plant		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Watkins Roofing				
Address: 218 N Wheatley st				
City: Ridgeland		State: MS	Zip: 39157	
Contact: Michael Dier			Tel: 601-706-8358	
ASBESTOS REMOVAL CONTRACTOR: Jeff Evans, Inc d/b/a Eagle Construction				
Address: 1450 Old Brandon Rd				
City: Flowood		State: MS	Zip: 39232	
Contact: Chuck Womack			Tel: 601-940-5411	
Certification Number: ABC-1799		Expiration Date: 3/4/2023 3/01/2025		
OTHER OPERATOR: Hodges Land Services				
Address: 825 Highway 12 W				
City: Kosciusko		State: MS	Zip: 39090	
Contact: Caine Dearman			Tel: 601-672-2086	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 8-28-24	
Inspector: William Faulkner		Certification Number: ABI-11986	Expiration Date: 9-15-24 9/05/2025	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: PLM - Transite,brick motar,insulation,floor tile, ceiling tile caulking, roofing, sheetrock				
VII. QUANTITY OF RACM TO BE REMOVED: 2,500s/f transite,2,000s/f ceiling,90l/f insulation, 160l/f caulk				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10-21-24			Complete: 11-10-24	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 10-21-24			Complete: 12-30-24	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Removal of asbestos containing materials with hand tools

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Stop work and notify competent person, keep wet, seal all critical barriers & put under negative pressure

XIII. WASTE TRANSPORTER #1

Name: ADS, Inc

Address: P. O. Box 1296

City: Clinton

State: MS

Zip: 39060-1296

Contact Person: Mark Parkman

Tel: 601-925-0507

WASTE TRANSPORTER #2

Name: Eagle Construction

Address: 1450 Old Brandon Rd

City: Flowood

State: MS

Zip: 39232

Contact Person: Chuck Womack

Tel: 601-940-5411

XIV. WASTE DISPOSAL SITE

Name: Little Dixie Landfill

Address: 1716 North County Line Rd

City: Ridgeland

State: MS

Zip: 39157

Contact Person:

Tel: 601-982-9488

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

Stop work & notify owner, keep wet and double bag immediately

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Chuck Womack
Type or Print Name


(Signature of Owner/Operator)

10.03.24
(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Chuck Womack
Type or Print Name


(Signature of Owner/Operator)

10.03.24
(Date)



Legend

⊙ Sample Location



Hodges Land Service
 N 32° 02' 13.2" W 90° 13' 12.17"
 135 North Wheatley Street
 Hattiesburg, MS 39157

Drawing #:	Figure 2	
Drawing Name:	Site Aerial Map	
Project:	Asbestos Inspection	
Map Source:	Google Earth	
Date Drawn:	9/5/2024	Drawn By: TF